

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 330509



Photo #1

Sooner Unit 21-6-15 (05-123-19226) Wellsite

Bradenhead NOT plumbed to surface

Stained soil

Unused Equipment

prior insp.



Photo #2

Sooner Unit 21-6-15 Wellsite

Bradenhead NOW plumbed to surface

Stained soil

Unused Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SEnw

Location #: 330509



Photo #3
Sooner Unit 21-6-15 Wellsite

Stained soil
Unused Equipment
prior insp.



Photo #4
Sooner Unit 21-6-15 Wellsite

Stained soil
Unused Equipment

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 330509



Photo #5

Sooner Unit 21-6-15 Wellsite

Unused Equipment

prior insp.



Photo #6

Sooner Unit 21-6-15 Wellsite

Sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SEnw

Location #: 330509



Photo #7

Sooner Unit Battery | Facility

from recent insp.