

Inspection Photos
Location Name: Wagner 11-65-11-1H
Location ID: 421908



Photo 1 – Pumping Unit



Photo 2 – Propane Tank, missing labels.

Inspection Photos
Location Name: Wagner 11-65-11-1H
Location ID: 421908



Photo 3 – 4 strings of Tubing




Photo 4 – Trash at Wellhead

Inspection Photos
Location Name: Wagner 11-65-11-1H
Location ID: 421908




Photo 5 – Stained Soil at Wellhead




Photo 6 – Stained Soil at Arrow Engine