

Inspection Photos
Operator Name: CAERUS Piceance LLC
Location ID: 334643



Pin hole at 6 o'clock position on tee



2" Dump line, leak discovered at tee