

Inspection Photos  
Location Name: Mleynak, Jack A #4  
Location ID: 318367



Photo 1 loc pic Weeds in and around well head and PU.



Photo 2 WH sign. Weeds around well head and PU.

**Inspection Photos**  
**Location Name: Mleynak, Jack A #4**  
**Location ID: 318367**



**Photo 3 Stained soil around well head. Weeds around WH.**



**Photo 4 Weeds in and around electric panel**

**Inspection Photos**  
**Location Name: Mleynak, Jack A #4**  
**Location ID: 318367**



**Photo 5 Noxious weeds not controlled around electric panel.**