

Inspection Photos
Location Name: Jilson #3
Location ID: 336406



**Photo 1 Well head sign. Weeds and Unused equipment:
Horses head and PU.**



Photo 2 Weeds and Unused equipment PU



Inspection Photos
Location Name: Jilson #3
Location ID: 336406



Photo 3 Well is TA. PU is disassembled Flow lines from WH have been disconnected. TA status submitted to COGCC 8-6-15. No MIT on file.