

Maralex Resources Inc.
API # 077-08313
Inspection # 696600422



Photo #1 . No Battery sign at tank battery or at entrance of location, Battery sign is at wellhead

Caerus Piceance LLC
API # 045-0942510417
Inspection # 696600422



Photo #2 Photo at entrance of location .

Photo #3 Photo at entrance of location

Maralex Resources Inc.
API # 077-08313
Inspection # 696600422



Photo #4 Photo of pit. Weed around and inside of pit.

Photo #5 photo of wellheads.

Maralex Resources Inc.
API # 077-08313
Inspection # 696600422



Photo #6 Unused equipment on location by wellhead



Photo #7 Weeds on location

Maralex Resources Inc.
API # 077-08313
Inspection # 696600422



Photo #8 Weeds on location around separator burner

Photo #9 Weeds on location around separator burner

Caerus Piceance LLC
API # 045-0942510417
Inspection # 696600422



Photo #10 Weeds on location and around burner



Photo #11 Weeds on location and in pit