

Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #1 . No Battery sign at tank battery or at entrance of location, This sign is at the wellhead .**

Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



Photo #2 Photo at entrance of location .



Photo #3 Photo at entrance of location



**Maralex Resources Inc.**  
**API # 077-083423**  
**Inspection # 696600425**



**Photo #4 Photo of the tank battery**



**Photo #5 photo of the wellheads.**

Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #6 Erosion channel on location moving sediment on North side off location.**



**Photo #7 Erosion channel moving sediment off North side location, choking out vegetation**



Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #8 weeds on and around location**



**Photo #9 Weeds on and around location and in pit**



Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #10 Trash on and around location**



**Photo #11 Trash on and around location**



Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



Photo #12 Trash on and around location



Photo #13 Photo of trash on location



Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #14 Erosion moving sediment off location by tank battery**



**Photo #15 Erosion moving sediment off location by tank battery. Vegetation is being choked out**



Maralex Resources Inc.  
API # 077-083423  
Inspection # 696600425



**Photo #16 Berm around tank is in need of maintenance.  
Containment does not comply with COGCC regulations**



**Photo #17 Berm around tank is in need of maintenance.  
Containment does not comply with COGCC regulations**