

Maralex Resources Inc.

API # 077-08410

Inspection # 696600427



Photo #1 Battery sign is at the wellhead .

Maralex Resources Inc.
API # 077-08410
Inspection # 696600427



Photo #2 Photo at entrance of location . Weeds and Debris on location



Photo #3 Photo at entrance of location. Weeds and Debris on location

Maralex Resources Inc.
API # 077-08410
Inspection # 696600427



Photo #4 Photo of battery sign



Photo #5 photo of the wellheads. No lubrication top. Well is open to atmosphere. Needs LOTO

Maralex Resources Inc.
API # 077-08410
Inspection # 696600427



Photo #6 Un-used risers on location need marked and LOTO



Photo #7 Un-used risers on location need marked and LOTO

Maralex Resources Inc.
API # 077-08410
Inspection # 696600427



Photo #8 Perimeter ditch used as a BMP is in need of maintenance.



Photo #9 Perimeter ditch and sediment trap used as a BMP is in need of maintenance.