

Inspection Photos  
Location Name: MINE DUMP 44-33  
API#: 05-071-07722  
INSP. #: 695101151



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



## Inspection Photos

Location Name: MINE DUMP 44-33

API#: 05-071-07722

INSP. #: 695101151



**PHOTO 3: TRASH ON LOCATION. COMPLY WITH RULE 603. CA  
DATE 8/11/19**

**PHOTO 4: TRASH ON LOCATION. COMPLY WITH RULE 603. CA  
DATE 8/11/19**