

Inspection Photos
Location Name: MOLTREER 31-7 FOLLOWUP
API#: 05-071-06522
INSP. #: 695101153



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: MOLTRER 31-7 FOLLOWUP

API#: 05-071-06522

INSP. #: 695101153



**PHOTO 3: APPEARS THAT THERE IS NO BRADENHEAD.
APPEARS TO BE A 7" COLLAR LOOKING UP WITH 4 ½"
PRODUCTION CSG INSIDE. APPEARS TO HAVE CMT ABOUT 1'
DOWN INSIDE 7" SRF CSG.**