

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

C

AUG 24 1995



99999999

FACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05-011 - 6004

LEASE NAME: ELSTON ET AL #1

LOCATION: NENE 24-24S-51W

OPERATOR: RIDDLE & GOTTLIEB

DATE: 8-17-95

INSPECTOR: R. VanSickle

Insp. Type: SR

Insp. Status: DA

PA: Y N

Pass/Fail: P F

Viol.: Y N

NOV: Y N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)	—	
Pits (Reserve/Production) (Rule 902, 903, 904)	—	
Fences (Rule 604.C.(3), 1003.A)	—	
Tank Battery Equipment (Rule 604)	—	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	Pit open & site revegetated, The light sandy soil & low rainfall don't warrant reclamation. At times the pit, situated such that rain water can run in, holds water and is probably a water hole for cattle in spring. Recommend no reclamation work be done.	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

BEST IMAGE
AVAILABLE

White - File Green - Operator Canary - Well Site



00575212