

Inspection Photos

API: 05-055-06064

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06064 | Date: 8/1/2019

Inspection Photos



Photo 1. There are numerous noxious weeds (Diffuse knapweed) near all the wells in this area. Noxious weeds were not properly controlled in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06064 | Date: 8/1/2019