

**Inspection Photos**  
**Location Name:** Horsetail /19N-1924M-R  
**Location #:** 438078



Colorado Oil & Gas Conservation Commission  
40.81884, -103.79419, 1425.0m, 48°  
08/01/2019 11:40:08 AM



Colorado Oil & Gas Conservation Commission  
40.81893, -103.79409, 1426.0m, 13°  
08/01/2019 11:41:12 AM

**Photo #1**  
**Horsetail 19N-1924M-R (05-123-40630) UIC - Wellsite**  
**Not Injecting**  
**Temporary Shut-In | SI**  
**Injection pump filter maintenance**  
**Weeds**

**Photo #2**  
**Horsetail 19N-1924M-R UIC - Wellsite**  
**Tbg. Press: (-13.58#, vacuum)**

**Inspection Photos**  
**Location Name:** Horsetail /19N-1924M-R  
**Location #:** 438078



**Photo #3**  
**Horsetail 19N-1924M-R UIC - Wellsite**  
**Csg. Press: 199#**



**Photo #4**  
**Horsetail 19N-1924M-R UIC - Wellsite**  
**Bradenhead Press: Bull plugged**



**Inspection Photos**  
**Location Name:** Horsetail /19N-1924M-R  
**Location #:** 438078



**Photo #5**  
**Horsetail 19N-1924M-R UIC - Disposal Facility**  
**Crude Oil Tanks - Loadouts**  
**Stained soil**



**Photo #6**  
**Horsetail 19N-1924M-R UIC - Disposal Facility**  
**Crude Oil Tanks - Drain lines**  
**Stained soil**

**Inspection Photos**  
**Location Name:** Horsetail /19N-1924M-R  
**Location #:** 438078



Colorado Oil & Gas Conservation Commission  
40.83335, -103.82543, 119°  
08/01/2019 12:06:21 PM

**Photo #7**

**Horsetail 19N-1924M-R UIC - Disposal Facility**  
**Injection pumps**



Colorado Oil & Gas Conservation Commission  
40.81826, -103.79494, 1422.0m, 0°  
08/01/2019 11:37:43 AM

**Photo #8**

**Horsetail 19N-1924M-R UIC - Disposal Facility**  
**Entrance sign & Facility**