

# Inspection Photos

API: 05-055-06035

Operator: OXY USA INC

Inspection Date: 8/1/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06035 | Date: 8/1/2019

## Inspection Photos



**Photo 2.** The operator name on well sign is has been updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 8/1/2019

## Inspection Photos



**Photo 3.** Facing northeast toward the fenced pit. There are numerous noxious weeds (Canada thistle) in this area that have not been controlled since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 8/1/2019

## Inspection Photos



**Photo 3.** Facing northwest toward the fenced pit area. There are numerous noxious weeds (Canada thistle) in this area that have not been controlled since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06035 | Date: 8/1/2019