

Inspection Photos
Location Name: Cosslett #1
Location ID: 317996



Photo 1 WH



Photo 2 WH sign faded not legible

Inspection Photos
Location Name: Cosslett #1
Location ID: 317996



Photo 3 Stained soil around WH. Mechanical issue: appears packing is leaking.