

Inspection Photos
Location Name: James S. Haley Trustee B1
Location ID: 318160



Photo 1 lease road weeds



Photo 2 WH



Inspection Photos
Location Name: James S. Haley Trustee B1
Location ID: 318160



Photo 3 WH sign



Photo 4 Pump jack



Inspection Photos
Location Name: James S. Haley Trustee B1
Location ID: 318160



Photo 4 Mechanical issue leaking grease zirk