

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2019

Submitted Date:

08/05/2019

Document Number:

696200522**FIELD INSPECTION FORM**

Loc ID 437222	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96155</u> Name of Operator: <u>WHITING OIL & GAS CORPORATION</u> Address: <u>1700 BROADWAY STE 2300</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80290</u>				Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437223	WELL	AL	05/03/2019	LO	123-39455	Razor 10F-1511A	RI
437224	WELL	AL	05/03/2019	LO	123-39456	Razor 10F-1512B	RI
437225	WELL	AL	05/03/2019	LO	123-39457	Razor 10F-1509A	RI
437258	WELL	AL	05/03/2019	LO	123-39459	Razor 10F-1510B	RI
437713	WELL	AL	05/03/2019	LO	123-39646	Razor 10F-0306B	RI
437720	WELL	AL	05/03/2019	LO	123-39650	Razor 10F-1508B	RI
437723	WELL	AL	05/03/2019	LO	123-39651	Razor 10F-0308B	RI
437725	WELL	AL	05/03/2019	LO	123-39653	Razor 10F-1507A	RI
437748	WELL	AL	05/03/2019	LO	123-39665	Razor 10F-0312B	RI
437749	WELL	AL	05/03/2019	LO	123-39666	Razor 10F-0309A	RI
437750	WELL	AL	05/03/2019	LO	123-39667	Razor 10F-0311A	RI
437755	WELL	AL	05/03/2019	LO	123-39669	Razor 10F-0310B	RI
437772	WELL	AL	05/03/2019	LO	123-39682	Razor 10F-0305A	RI
437780	WELL	AL	05/03/2019	LO	123-39689	Razor 10F-0307A	RI
437781	WELL	AL	05/03/2019	LO	123-39690	Razor 10F-1506B	RI
437784	WELL	AL	05/03/2019	LO	123-39692	Razor 10F-1505A	RI

General Comment:

This is a final reclamation and stormwater inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>437223</u>	Type: <u>WELL</u>	API Number: <u>123-39455</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437224</u>	Type: <u>WELL</u>	API Number: <u>123-39456</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437225</u>	Type: <u>WELL</u>	API Number: <u>123-39457</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437258</u>	Type: <u>WELL</u>	API Number: <u>123-39459</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437713</u>	Type: <u>WELL</u>	API Number: <u>123-39646</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437720</u>	Type: <u>WELL</u>	API Number: <u>123-39650</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437723</u>	Type: <u>WELL</u>	API Number: <u>123-39651</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437725</u>	Type: <u>WELL</u>	API Number: <u>123-39653</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437748</u>	Type: <u>WELL</u>	API Number: <u>123-39665</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437749</u>	Type: <u>WELL</u>	API Number: <u>123-39666</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437750</u>	Type: <u>WELL</u>	API Number: <u>123-39667</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437755</u>	Type: <u>WELL</u>	API Number: <u>123-39669</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437772</u>	Type: <u>WELL</u>	API Number: <u>123-39682</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437780</u>	Type: <u>WELL</u>	API Number: <u>123-39689</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437781</u>	Type: <u>WELL</u>	API Number: <u>123-39690</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>437784</u>	Type: <u>WELL</u>	API Number: <u>123-39692</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** No disturbance /Location never built Pass

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Operator submitted Sundry Form 4s for wells on location stating location has not been constructed or wells drilled. Unable to find evidence of Oil and Gas disturbance.
T-Posts used as well markers have been left on the location and will need to be removed.

Corrective Action: Remove well markers Date **08/23/2019**

Overall Final Reclamation	In Process	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	------------	----------------------------------------------------------	----------------------------------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200523	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4900908