FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

   1 CA Completed
   0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 56680

Name of Operator: MERRION OIL & GAS CORP

Address: 610 REILLY AVENUE

City: FARMINGTON   State: NM   Zip: 87401

Contact Name and Telephone:

Name:

Phone: ( )   Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Thompson, Philana	505-486-1171	pthompson@merrion.bz
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us

COGCC INSPECTION SUMMARY:

  FIR Document Number: 679704490

  Inspection Date: 06/13/2019   FIR Submit Date: 06/14/2019   FIR Status:

Inspected Operator Information:

  Company Name: MERRION OIL & GAS CORP   Company Number: 56680

  Address: 610 REILLY AVENUE

  City: FARMINGTON   State: NM   Zip: 87401

LOCATION - Location ID: 316096

  Location Name: PARK MOUNTAIN-63S103W   Number: 18NWNE   County: RIO BLANCO

  Qtrqtr: NWNE   Sec: 18   Twp: 3S   Range: 103W   Meridian: 6

  Latitude: 39.791700   Longitude: -108.996790

FACILITY - API Number: 05-103-   -00   Facility ID: 232109

  Facility Name: PARK MOUNTAIN   Number: 31-18

  Qtrqtr: NWNE   Sec: 18   Twp: 3S   Range: 103W   Meridian: 6

  Latitude: 39.791700   Longitude: -108.996790

`CORRECTIVE ACTIIONS:

1	CA# 126152

Corrective Action: Install sign to comply with Rule 210.b.   Date: 08/12/2019

      Response: CA COMPLETED   Date of Completion: 08/02/2019

Operator Comment: nearest CR added to sign

| COGCC Decision: | _____ |
| COGCC Representative: | |

OPERATOR COMMENT AND SUBMITTAL

| Comment: | |

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Philana Thompson   Signed: _____

Title: Regulatory Compliance   Date: 8/6/2019 2:48:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files