

Final Reclamation Inspection

July 31, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 322634

Inspection Document #: 697500406

Weld County, CO

SWSE Section 33 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAVIS #2-33
Location ID: 322634



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates a List B Colorado noxious weed, Musk thistle. Operator indicated that additional reclamation was performed; however, little germination of desirable species was observed.



Photo 2. Photo taken from the central location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: DAVIS #2-33
Location ID: 322634



Photo 3. Close up photo taken from the central location. Photo illustrates little germination of desirable species.



Photo 4. Reference photo taken northeast of location, facing Northeast. Photo illustrates the location is not reflective of reference area vegetative levels.