

# Final Reclamation Inspection

July 31, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 329319

Inspection Document #: 697500408

Weld County, CO

SESE Section 33 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DAVIS #33-16  
Location ID: 329319



**Photo 1.** Photo taken from the entrance of location, facing North. Photo illustrates the Operator has failed to reclaim the access road. COGCC staff did not inspect the tank battery or well location which would be at the end of this access road based on aerial imagery.