

Final Reclamation Inspection

July 31, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 329318

Inspection Document #: 697500412

Weld County, CO

SENE Section 33 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAVIS #33-8
Location ID: 329318



Photo 1. Photo taken from the eastern location, facing South. Photo illustrates Operator has performed final reclamation activities and appears to be performing weed management.



Photo 2. Photo taken from the central location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DAVIS #33-8
Location ID: 329318



Photo 3. Reference photo taken along the southern location, facing South.




Photo 4. Photo taken along the approach entrance to location, facing South. Operator has failed to reclaim the approach and erosion was observed.