

Inspection Photos

Location Name: SOONER UNIT-68N58W /28SENW

Location #: 330480



Photo #1

Sooner Unit 28-6-1 (05-123-19173) Wellsite

Bradenhead NOT plumbed to surface

Stained soil

Unused Equipment

prior insp.



Photo #2

Sooner Unit 28-6-1 Wellsite

Temporarily Abandoned | TA

Bradenhead NOW appears plumbed to surface

Stained soil appears mitigated

Unused Equipment remains on site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SOONER UNIT-68N58W /28SENW

Location #: 330480



Photo #7

Sooner Unit Battery | Facility

from recent insp.