

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SWNW

Location #: 327558



Photo #1

Sooner Unit 5-21 (05-123-14850) Wellsite

Bradenhead NOT plumbed to surface

prior insp.



Photo #2

Sooner Unit 5-21 Wellsite

Shut-In | SI

Bradenhead NOW appears plumbed to surface

Inspection Photos

Location Name: SOONER UNIT-68N58W /21SWNW

Location #: 327558



Photo #3

Sooner Unit Battery | Facility

from recent insp.