

Final Reclamation Inspection

July 31, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 323448

Inspection Document #: 697500414

Weld County, CO

SWNW Section 34 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WILLIAMS #2-34
Location ID: 323448



Photo 1. Photo taken from the entrance of the tank battery location, facing East. Photo illustrates the Operator has failed to reclaim the tank battery location and a portion of the access road to the well location. COGCC staff did not inspect the entire access road to the well location or the well location.