

# Final Reclamation Inspection

July 31, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 329304

Inspection Document #: 697500416

Weld County, CO

NWNW Section 34 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: TENNYSON #34-4  
Location ID: 329304



**Photo 1.** Photo taken from location, facing North. Photo illustrates Operator has failed to reclaim the access road.



Inspection Photos  
Location Name: TENNYSON #34-4  
Location ID: 329304



**Photo 2.** Photo taken from the south entrance to the tank battery location, facing South. Photo illustrates Operator has failed to remove the culvert.



**Photo 3.** Photo taken from the south entrance to the tank battery location, facing North. See comments under Photo 2.



Inspection Photos  
Location Name: TENNYSON #34-4  
Location ID: 329304



**Photo 4.** Photo taken along the northern tank battery location, facing North. Photo illustrates a portion of no or stunted crop growth.



Inspection Photos  
Location Name: TENNYSON #34-4  
Location ID: 329304



**Photo 5.** Photo taken along the northern tank battery location, facing South. See comments under Photo 4.



Inspection Photos  
Location Name: TENNYSON #34-4  
Location ID: 329304



**Photo 6.** Reference photo taken northwest of location, facing West. Photo illustrates disturbance areas are not reflective of reference crop vegetative levels.