

# Final Reclamation Inspection

July 31, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 329360

Inspection Document #: 697500418

Weld County, CO

SESE Section 28 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DOERING #28-16  
Location ID: 329360



**Photo 1.** Photo taken from a portion of the well location access road, facing North. Crop growth appears to be reflective of reference area vegetation.



Inspection Photos  
Location Name: DOERING #28-16  
Well Location ID: 329360



**Photo 2.** Photo taken from the battery location, facing West. Operator has removed the equipment but has failed to control weeds throughout the location.



**Photo 3.** Photo taken from the battery location, facing East. See comments under Photo 2.