

## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



Production facility



Wellheads

## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #3 Unused equipment**



**Photo #4 Unused equipment**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #5 Crude oil tank placards**



**Photo #6 Produced water vault placards**

## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #7 Load line leak**



**Photo #8 Load line leak**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #9 Trash**



**Photo #10 Trash**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #11 Unused equipment**



**Photo #12 Location erosion**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #13 Location erosion**



**Photo #14 Location erosion**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #15 Location erosion**



**Photo #16 Location erosion**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



**Photo #17 Location erosion**



**Photo #18 Location erosion**



## Inspection Photos

Location Name: Five Rivers K 18-69 HN, Five Rivers K 7-62-1 HN

Facility ID: 434273 and Facility ID: 434306



Colorado Oil & Gas Conservation Commission  
40.32094, -104.79298, 1429.0m, 16°  
08/08/2019 11:42:58 AM

**Photo #19 Trash**



Colorado Oil & Gas Conservation Commission  
40.3208, -104.79326, 1423.0m, 286°  
08/08/2019 11:34:10 AM

**Photo #20 Unused equipment**