

Inspection Photos
Location Name: Bernhart 13-14
Location ID: 329391



Production facility

Inspection Photos
Location Name: Bernhart 13-14
Location ID: 329391



Produced water vault placard on 7/24/19



Produced water vault placard on 8/8/19

Inspection Photos
Location Name: Bernhart 13-14
Location ID: 329391




Wellhead sign on 7/24/19



Wellhead sign on 8/8/19

Inspection Photos
Location Name: Bernhart 13-14
Location ID: 329391



Master valve on 7/24/19



Master valve on 8/8/19

Inspection Photos
Location Name: Bernhart 13-14
Location ID: 329391



Stained soil on 7/24/19



Stained soil on 8/8/19