

Southwest Rangely 4-17-1-2

API: 05-103-09475

Inspection: 679704985



Photo 1. Location.

Southwest Rangely 4-17-1-2

API: 05-103-09475

Inspection: 679704985



COGCC  
39.96661, -108.87356, 6019.6ft, 225°  
08/07/2019 06:14:32 PM

Photo 2. Tank.



COGCC  
39.96667, -108.87345, 6015.9ft, 157°  
08/07/2019 06:15:57 PM

Photo 3. Battery sign.

Southwest Rangely 4-17-1-2

API: 05-103-09475

Inspection: 679704985



**Photo 4. Uncapped riser next to separator.**