

Inspection Photos
Location Name: Lazy 15-8
Location ID: 331680



Pic 1



Pic 2 possible leak at wellhead

Inspection Photos
Location Name: Lazy 15-8
Location ID: 331680



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.14885, -104.57133, 4810.9ft, 321°
08/08/2019 11:00:55

Pic 3 possible leak at wellhead



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.14873, -104.57159, 4814.0ft, 208°
08/08/2019 11:02:09

Pic 4

Inspection Photos
Location Name: Lazy 15-8
Location ID: 331680



Pic 5



Pic 6