

**Inspection Photos**  
**Location Name: McCallum Unit 70**  
**Location ID: 324617**

**Form 21**  
**MECHANICAL INTEGRITY TEST**

**State of Colorado**  
**Oil and Gas Conservation Commission**

**MECHANICAL INTEGRITY TEST**

**OSCC Operator Number:** 48290

**Name of Operator:** KPI/Kalman Company, Inc. **Operator Name:** Susana Lara-Mesa

**Address:** 1675 Broadway, STE 5800 **Phone:** (303) 825-4822

**City:** Denver **State:** CO **OSCC License Number:** 60202 **OSCC License Holder:** Susana Lara-Mesa

**Well Number:** 05-557-28048 **Well Completion Number:** 213155

**Well Name:** MCCALLUM UNIT **Well Test Number:** 70

**License Number:** 56399 **Category:** 10R1 **Range:** 790V **Well Class:** S **Well Test Date:** 08/02/2019

SHUT-IN PRODUCTION WELL  INJECTION WELL

**Test Type:**

Leak to Atmosphere (LTA)  Leak to Surface (LTS)  Leak to Water (LW)  Leak to Land (LL)  Leak to Air (LA)  Leak to Ground (LG)  Leak to Other (LO)

**Wellhead Data at Time of Test:**

**Wellhead Name:** PIERRE B 1558-1580

**Wellhead Depth:** 1303 **Wellhead Pressure:** 1303

**Wellhead Type:** 2 3/8" **Wellhead Material:** 1303

**Wellhead Test Date:** 08/02/2019 **Wellhead Test Type:** SHUT-IN

**Wellhead Test Results:**

Wellhead Test Type	Wellhead Test Result	Wellhead Test Pressure (psi)	Wellhead Test Temperature (°F)
Leak to Atmosphere (LTA)	0 ps	740 ps	0 ps
Leak to Surface (LTS)	0 ps	740 ps	0 ps
Leak to Water (LW)	0 ps	740 ps	0 ps
Leak to Land (LL)	0 ps	740 ps	0 ps
Leak to Air (LA)	0 ps	740 ps	0 ps
Leak to Ground (LG)	0 ps	740 ps	0 ps
Leak to Other (LO)	0 ps	740 ps	0 ps

**Inspector Name:** Tessa Buxley **Inspector Title:** Production Authorized

**OSCC License Number:** 60202 **OSCC License Holder:** Susana Lara-Mesa **Inspector Title:** Field Inspector

**Inspection Document Number:** 0689802962

**08.02.2019 11:48**

**Photo 1. Photo of Form 21 as filled out and signed in the field.**