

Laramie Energy LLC
API # 077-08655
Inspection # 696600450



Photo #1 Battery sign is posted at the entrance to location

Inspection # 696600450



Photo #2 Photo at entrance of location.




Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-08655
Inspection # 696600450



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC
API # 077-08655
Inspection # 696600450



Photo #6 Weeds on location and around wellhead need removed



Photo #7 Weeds on location and around wellhead need removed

Laramie Energy LLC
API # 077-08655
Inspection # 696600450



Photo #8 Sediment traps on access road need maintenance



Photo #9 Sediment traps on access road need maintenance

Laramie Energy LLC
API # 077-08655
Inspection # 696600450



Photo #10 Check dams on access road need maintenance



Photo #11 Check dams on access road need maintenance