

Inspection Photos

API# 103-01008

Operator: Chevron

Inspection Number: 692401237

Inspection Date: 8/2/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Open Valve Can at road junction to Northeast of Chevron Office.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Fee 50 API# 103-01008



Photo#2:
Desiccated rabbit carcasses at bottom of cellar.

August 2, 2019



Photo#3:
Desiccated rabbit carcasses at bottom of cellar.