

Inspection Photos

API: 05-071-07416

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 8/8/2019

Inspection Photos



Photo 1. Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 8/8/2019

Inspection Photos



Photo 2. Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 8/8/2019

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 8/8/2019