



Certificate of Pipeline Inspection

In accordance with COGCC Rule 1102.h, this Certificate of Pipeline Inspection is to be completed by a third-party pipeline inspector prior to the pipeline named below being placed into service. By the execution of this Certificate, the pipeline inspector is certifying that the pipeline named below was installed as prescribed by the manufacturer's specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules, and that the certifying inspector has provided Noble Midstream with (i) all inspection records relating to the pipeline and (ii) copies of the inspector's training qualifications.

AFE/PROJECT NAME: 5000027

IDP: ☒ Mustang ☐ East Pony ☐ Wells Ranch ☐ Black Diamond ☐ Greeley Crescent

PIPELINE NAME: OSCAR I & II

NOMINAL O.D. DIAMETER (in): _____ LENGTH (ft): CONNECTION

MATERIAL: ☒ Steel ☐ HDPE ☐ Flex Steel

TYPE: ☒ Crude Oil ☐ Produced Water ☐ Natural Gas

LOCATION/COUNTY: WELD

ROUTE DESCRIPTION: LINE REVERSAL OSCAR TO TAMPA

I, ROGER LUCE hereby certify that the OSCAR I & II pipeline and all appurtenances were constructed and installed in accordance with all component manufacturing specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules.

CHIEF INSPECTOR

NAME: ROGER LUCE

SIGNATURE: [Signature]

COMPANY: MSLI

EMAIL AND CONTACT NUMBER: LUCEINSPECTION@GMAIL.COM

DATE: 7/20/18

NOBLE MIDSTREAM CONSTRUCTION SUPERVISOR or CONSTRUCTION MANAGER

NAME: ROGER LUCE

SIGNATURE: [Signature]

DATE: 7/20/18

Completed forms must be included in the construction job books and a copy sent to Matt Cummings in EHSR for filing with COGCC. Form must be completed by PSSR date.