

Inspection Photos

API# 103-09273

Operator: Chevron

Inspection Number: 692401235

Inspection Date: 8/2/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest and Chevron Office building.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron AL Fee 148Y API# 103-09273



Photo#2:
Grated Cellar/ Vault.



Photo#3:
Conductor set inside Cellar.

August 2, 2019