



### Certificate of Pipeline Inspection

In accordance with COGCC Rule 1102.h, this Certificate of Pipeline Inspection is to be completed by a third-party pipeline inspector prior to the pipeline named below being placed into service. By the execution of this Certificate, the pipeline inspector is certifying that the pipeline named below was installed as prescribed by the manufacturer's specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules, and that the certifying inspector has provided Noble Midstream with (i) all inspection records relating to the pipeline and (ii) copies of the inspector's training qualifications.

AFE/PROJECT NAME: 5000308/Mustang IOP Phase 2 DP-411 6" Produced Water Line

IDP: ☒ Mustang ☐ East Pony ☐ Wells Ranch ☐ Black Diamond ☐ Greeley Crescent

PIPELINE NAME: DP-411 6" Produced Water Line

NOMINAL O.D. DIAMETER (in): 6.931" LENGTH (ft): 1142.3'

MATERIAL: ☐ Steel ☐ HDPE ☒ Flex Steel

TYPE: ☐ Crude Oil ☒ Produced Water ☐ Natural Gas

LOCATION/COUNTY: Weld County

ROUTE DESCRIPTION: (16k PW Skid) DP-411 to 20" DCP Tie-in Site

I, David Martini hereby certify that the DP-411 6" Produced Water pipeline and all appurtenances were constructed and installed in accordance with all component manufacturing specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules.

#### CHIEF INSPECTOR

NAME: David Martini

SIGNATURE: David Martini

COMPANY: MDLT

EMAIL AND CONTACT NUMBER: red.martini@mdl-sves.com 918-760-8980

DATE: 8/5/2019

#### NOBLE MIDSTREAM CONSTRUCTION SUPERVISOR or CONSTRUCTION MANAGER

NAME: Brock Allen

SIGNATURE: Brock Allen

DATE: 8/5/2019

Completed forms must be included in the construction job books and a copy sent to Matt Cummings in EHSR for filing with COGCC. Forms must be completed by PSSR date.