

Inspection Photos

08/08/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 327361
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 1: Photo taken from the east/west access road, facing west. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established along the access roads.



Photo 2: Photo taken from the east/west access road, facing west (approximately 40.650112° , -103.860646°). Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established along the access roads. Photo also shows stormwater erosion degradation and sediment transport from the access road. Operator has failed to conduct sufficient stormwater management in accordance with 1002.f

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 3: Continued from photo 2.



Photo 4: Photo taken from the east/west access road, facing west. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established along the access roads

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 5: Photo taken from north end of the location, facing south. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location/access road.



Photo 6: Photo taken from the northwest end of the location, facing south. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 7: Continued from photo 6.



Photo 8: Photo taken from the east end of the location, facing south. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 9: Photo taken from the south end of the location, facing west. See comments under photo 5.



Photo 10: Photo taken from the south end of the location, facing northwest. See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 327361



Photo 11: Photo taken from the interim areas of the location. Photo shows Diffuse Knapweed

