



99999999

Interoffice OGCC-1
Rev. 7/8/55

VERBAL REQUESTS

NOTICE OF INTENTION TO DRILL _____

Bonding Status _____

NOTICE OF INTENTION TO ABANDON X _____

OTHER _____

| | | | |
|--|--|---|--|
| | | | |
| | | 3 | |
| | | | |
| | | | |

COMPANY W. H. Carpenter BY Bill Carpenter

ADDRESS _____ Title _____

LEASE Carpenter & Grant Pector Estate WELL NUMBER 1
United Guaranty

COUNTY Rio Blanco FIELD Rosely Area

LOCATION - By Quarters lot 2 Sec. 3 Twp. 1N R. 102W Mer. 6[±]PM
425' So. of N. lot 360' E of W. lot line

The Well is located _____ ft. (N) of Section Line, and _____ ft. (E) of Section Line.
(S) (W)

DETAILS OF PLAN OF WORK: T.D. 2340 FORMATION Manassas

ESTIMATED DATE OF WORK: 3-17-59 ESTIMATED TIME: 4PM

found fault at ±1950' no water
Drill ~~out~~ plug in top of pipe - 150'
Manassas shale well
drilled with size & got cemented lost circulation
material

APPROVED BY: W. R. Smith
DWR

DATE 3-17-59



00566543

103 - 46240

