

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

696300408**FIELD INSPECTION FORM**Loc ID 425393 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------------|---------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 425377 | WELL | SI | 05/01/2018 | OW | 123-34361 | Booth USX EE25-02D | SI |
| 425381 | WELL | SI | 09/01/2017 | OW | 123-34364 | Booth USX EE25-11D | SI |
| 425382 | WELL | SI | 09/01/2017 | OW | 123-34365 | Booth USX EE25-13D | SI |
| 425383 | WELL | SI | 09/01/2017 | OW | 123-34366 | Booth USX EE25-12D | SI |
| 425384 | WELL | SI | 09/01/2017 | OW | 123-34367 | Booth USX EE25-15D | SI |
| 425394 | WELL | PR | 10/01/2018 | OW | 123-34371 | Booth USX EE25-03D | PR |
| 425396 | WELL | SI | 11/01/2017 | OW | 123-34373 | Booth USX EE25-01D | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate (x7) | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel (x7) | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 7 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 7 | | |
| Comment: | All 7 appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |

| | | | |
|---------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 5 | 300 BBLS | STEEL AST | | 40.544100,-104.617170 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 5 | OTHER | BV CONCRETE | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBLS | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 425377 Type: WELL API Number: 123-34361 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 425381 Type: WELL API Number: 123-34364 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 425382 Type: WELL API Number: 123-34365 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 425383 Type: WELL API Number: 123-34366 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 425384 Type: WELL API Number: 123-34367 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 425394 Type: WELL API Number: 123-34371 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425396 Type: WELL API Number: 123-34373 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

COGCC Comments

| Comment | User | Date |
|------------------------------------|--------|------------|
| Routine Inspection | petrie | 08/08/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 696300409 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905067 |