

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



Photo #1 Battery sign is posted the entrance to location

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



Photo #2 Photo at entrance of location.



Photo #3 Photo at entrance of location.

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



**Photo #6 Weeds and Debris on location**



**Photo #7 Weeds and Debris on location**

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



**Photo #8 Weeds and Debris on location**



**Photo #Weeds and Debris on location**

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



**Photo #10. Erosion moving sediment off location at the entrance to location. No BMP's in place at time of inspection.**



**Photo #11. Erosion moving sediment off location at the entrance to location.**

Laramie Energy LLC  
API # 077-08456  
Inspection # 696600457



**Photo #12 Sediment is moving off location at entrance of location. Sediment is choking out vegetation**



**Photo #13 Sediment is moving off location at entrance of location. Sediment is choking out vegetation**