

Inspection Photos

Loc#315426

Operator: Chevron

Inspection Number: 692401254

Inspection Date: 7/31/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of location to Southeast over open wooden cellar/vault.

July 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Emerald Loc#315426



Photo#2:
Interim Reclamation areas are weedy.

July 31, 2019



Photo#3:
Interim Reclamation areas are weedy



Photo#4:
Sediment is collecting and migrating at base of Access Road.

July 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Emerald Loc#315426



Photo#5:
Erosion is occurring on both sides of access road.



Photo#6:
Erosion is occurring on both sides of access road

July 31, 2019