

RGU 23-23-198 PAD  
API: 05-103-11783 to 11789  
Inspection: 679705043



COGCC  
39.94706, -108.36259, 6490.2ft, 172°  
08/12/2019 03:03:12 PM

**Photo 1. Location.**

**RGU 23-23-198 PAD**  
**API: 05-103-11783 to 11789**  
**Inspection: 679705043**



**Photo 2. Separator & pig station.**



**Photo 3. Well head.**



RGU 23-23-198 PAD  
API: 05-103-11783 to 11789  
Inspection: 679705043

Condensate dripping



Photo 4. Tank battery.



Photo 5. Leaking valve and / or bull plug.