

Inspection Photos

API#103-10387

Operator: Eagle Operating

Inspection Number: 692401203

Inspection Date: 7/31/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of location to Southeast. Insert is of cellar installation at marker.

July 31, 2019



Photo#2:

Four Anchors remain on site, which has not been Reclaimed.

July 31, 2019



Photo#3:


Four Anchors remain on site, which is infested with desiccated ruderal weeds



Photo#4:

Four Anchors remain on site, which has not been reclaimed.

July 31, 2019



Photo#5:

Four Anchors remain on site which has not been de-compacted.