

Inspection Photos

API#103-10317

Operator: Eagle Operating

Inspection Number: 692400573

Inspection Date: 12/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

December 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald API#103-10317



Photo#2:
View to West from access road entry.

December 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald API#103-10317



Photo#3:
Looking out of Location to East.

December 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald API#103-10317