

Inspection Photos
Operator: BP America
Location/API #: 067-06949
Date: 8-12-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of erosional channel forming within the northeastern project area.



Photo 4. View of reference area vegetation, dominated by ponderosa pine (*Pinus ponderosa*) and gambel oak (*Quercus gambelii*).



COLORADO
Department of
Natural Resources