

Inspected Facilities

Facility ID: 240453 Type: WELL API Number: 123-08241 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 688401580 in response to FIRR #401982740. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	08/14/2019