

Inspected Facilities

Facility ID: 240646 Type: WELL API Number: 123-08434 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 688401553 in response to FIRR #401983996. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	08/14/2019