

Inspection Photos

Location Name: Horsetail 33M Location ID 436724

Inspection Date: 8/13/2019



Photo 1 – Photo of impacted material remaining on Horsetail 33M Pad.



Photo 2 – Photo of new produced water AST, no placards or capacity/contents labeling present.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources