

Inspection Photos

Location Name: Razor 26 SWD Location ID 440165

Inspection Date: 8/13/2019



Photo 1 – Photo of stormwater ditch on southside of pad near sample SS2 looking east. Water is stormwater from recent storm.



Photo 2 – Photo of outfall from stormwater retention pond.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Razor 26 SWD Location ID 440165

Inspection Date: 8/13/2019



Photo 1 – Photo of storm water detention pond southeast of Razor 26 SWD pad. Northwest corner of pond near soil samples SS-8/8A looking southeast.



Photo 2 – Photo of storm water detention pond southeast of Razor 26 SWD pad. Southeast corner of pond near soil samples SS-9/15 looking northwest. Sediment has accumulated on surface of pond water.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources